#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Yes

No

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015604 Address: 333 Burma Road **Date Inspected:** 07-Jul-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Chen Shi Gang, Yang Bai Qiang CWI Present: Yes No **Inspected CWI report:** Yes No N/A **Rod Oven in Use:** Yes No

Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** 

**Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

#### **Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG Bay 09, Deck Panel 13BW-DP3138(PL3334B)-001

This QA inspector performed conventional Ultrasonic Testing (UT) Inspection on deck panel tack weld areas. The inspection is preliminary prior to using the phased array (PAUT) testing system to verify indications found with conventional Ultrasonic testing. QA inspector performed UT on deck panel 13CE-DP3101-001, 15 ribs, 30 welds, 230 total tack welds inspected.

Weld 173 scanned 10 locations with 0 indications.

Weld 174 scanned 10 locations with 0 indications.

Weld 175 scanned 10 locations with 0 indications.

Weld 176 scanned 10 locations with 1 indication.

Weld 177 scanned 10 locations with 0 indications.

Weld 178 scanned 10 locations with 1 indication.

**BAY # 04** 

N/A

N/A

## WELDING INSPECTION REPORT

(Continued Page 2 of 2)

#### 13AE-DP3077-001

During random in process inspection this QA inspector observed that ZPMC personnel were performing repair welding on the Partial Joint Penetration (PJP) weld joint 001 of deck panel 13AW-DP3119-001. Welder is identified as 203805. ZPMC CWI is identified as Mr. Yang Bai Qiang. The welding variables recorded by QC appeared to comply with WPS-345-FCAW-2G(2F)-FCM-Repair. Attached photograph provides additional detail.

This Quality Assurance (QA) Inspector worked on Deck Panel Summary Log.

This Quality Assurance (QA) Inspector worked on Tack Weld Assessment sheets of deck panels of lift 13,

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



# **Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer